


# Humidifier Replacement Parts



## Elite Models 1000, 1000A, 1000M, 1000XM



| Item | Qty. Req'd | GFI # | Part Description                  |
|------|------------|-------|-----------------------------------|
| 1    | 1          | 7561  | 900 - 9 Nozzle                    |
| 2    | 1          | 7562  | 900 - 10 Spout                    |
| 3    | 1          | 7580  | GA4231 Orifice (Yellow) Pk of 12. |
| 4    | 1          | 7568  | P190 Compression Sleeve (Plastic) |
| 5    | 2          | 7565  | P101 Compression Nut              |
| 6    | 1          | 7563  | GA4235 Distributor Tube           |
| 7    | 1          | 7567  | P189 Brass Insert Tube            |
| 8    | 1          | 7566  | P102 Compression Sleeve (Copper)  |
| 8    |            | 7568  | P190 Compression Sleeve (Plastic) |
| 9    | 1          | 7564  | GA4004 Strainer screen            |
| 10   | 1          | 7222  | GA4045 Solenoid Valve             |
| 11   | 2          | 7941  | 900 - 40 Pad Rail                 |
| 12   | 1          | 7919  | GA19 Replacement Vapor Pad®       |
| 13   | 1          | 7571  | 900 - 14 Drain Pan                |
| 14   | 1          | 7570  | 900 - 15 Distributor Trough       |
| 15   | 1          | 7582  | GA4247 Fan Blade                  |

| Item                   | Qty. Req'd | GFI # | Part Description  |
|------------------------|------------|-------|---|
| 16                     | 1          | 7584  | GA4237 Motor  |
| 17                     | 1          | 7578  | 900 - 16 Name Plate   |
| 18                     | 1          | 7579  | 1000 - 11 Wiring Harness                                      |
| 19                     | 1          | 7586  | GA4238 Relay Circuit Board                                    |
| 20                     | 1          | 7346  | 1137 - 31 Power Supply Cord                                   |
| 21                     | 1          | 7950  | 950 - 1 Chasis  |
| 22                     | 2          | 7583  | 1000 - 1 Baffle   |
| <b>Parts Not Shown</b> |            |       |   |
|                        | 1          | 7585  | 1000 - 13 Front Cover   |
|                        | 1          | 7038  | MHX3C Manual Control, Wall / Duct Mount Humidistat (M Models) |
|                        | 1          | 7053  | WMH3 Wall Mount Housing                                       |
|                        | 1          | 7050  | GFX3 Automatic Digital Humidistat (1000, 1000A)               |
|                        | 1          | 7016  | GCV 3412 Code Valve (1000, 1000A)                             |

Humidifier Replacement Parts

1% 10 Days. Net 30 Days. F.O.B. Novi, Michigan \$3,000 Orders FFA